

Peldūdens kvalitātes mērījumi 2017. gadā

Datums	08.05. 2017.	23.05. 2017.	05.06. 2017.	19.06. 2017.	03.07. 2017.	17.07. 2017.	08.08. 2017.	22.08. 2017.	05.09. 2017.		08.09. 2017
--------	-----------------	-----------------	-----------------	-----------------	-----------------	-----------------	-----------------	-----------------	-----------------	--	----------------

Peldvieta PIE STADIONA











E. Coli skaits											
>2000/100 ml											
100 – 2000/100 ml						 100				 980	
<100/100 ml		 4	 1	 15	 20		 21	 17	 1		 25

Zarnu enterokoku skaits





















>100/100 ml										 490	
<100/100 ml		 2	 0	 31	 9	 69	 23	 16	 1		 7

DIENVIDRIETUMU peldvieta

E. Coli skaits											
100 – 2000/100 ml						 170				 330	
<100/100 ml		 3	 4	 16	 4		 20	 26	 4		

Zarnu enterokoku skaits											
>100/100 ml											
<100/100 ml											
		3	2	27	11	56	23	52	2	69	

Peldvieta Beberliņi

E. Coli skaits											
<100/100 ml											
		3	3	2	13	2	7	12	12	66	
Zarnu enterokoku skaits											
<100/100 ml											
		0	4	2	11	1	32	1	1	12	